Voids/Repairs Team

- Raise two orders on UHW= 1st order for removal works, 2nd order for air test (If necessary)
- Provide key location information
- Provide scope of works

Order goes to Council's Asbestos License Contractors for removal works

Asbestos License Contractor notifies HSE for notifiable works

HSE Notification

Asbestos survey report updated with sample results

Asbestos License Contractor

Carries out works

Asbestos License Contractor

Completes works

10% of works audited by Asbestos Manager/ Asbestos H&S Officer

External Analyst Laboratory

Council's Analyst contractor carries out air test (If necessary) and issues copies to Voids/Repairs Team and Asbestos Team and Asbestos License Contractor

1

Asbestos License Contractor

Contractor issues copies of removal documentation to Voids/Repairs Team and Asbestos Team



Asbestos Team

- O PSI updated
- O UHW updated



Voids/Repairs Team

Order Closed on UHW